

°C °F

 Automatic power conversion and display in Fahrenheit and Celsius when the iron's voltage source is 100-120V, or 220 - 240V.

Excluding Japan, Taiwan or some other countries where 110V in Celisus use.

+971 50 5227733

alliance.emirates@gmail.com www.alliancead.com